


# FAN COIL UNIT

(WALL MOUNTED TYPE)




## 1. Trouble-shooting:


Malfunction code	Malfunction
EE	Water-level alarm malfunction
E2	T2 evaporator sensor malfunction
E3	T1 evaporator sensor malfunction



**E2: T2 evaporator sensor malfunction**



**E3: T1 evaporator sensor malfunction**





Air Conditioning Systems

Cooling & Heating

**TRUST AIR-CONDITIONING EQUIPMENT CO.**

Shiraz office: 8 th floor, Alvand Blog., Dostan St.,  
Moaliabad Ave., SHIRAZ, IRAN., Post code: 71877-14446

Tel.: +98-71-36341070

Fax.: +98-71-36341094

Tehran office: No. 19- koohe nour St.- Motahhari St.-

TEHRAN, IRAN., Post code: 15876-73111

Tel.: +98-21-89389

Fax.: +98-21-88541903

Ahwaz office: No. 309- Kaveh St.- AHWAZ, IRAN., Post code: 61939-  
47911

Tel.: +98-61-32230647-8

Fax.: +98-61-32230647

E-mail: [info@trustacs.com](mailto:info@trustacs.com)

Web site: <http://www.trustacs.com>

پرتو پرتو در اولین جشنواره بین المللی  
برترین نام و نشان های تجاری ایران

