

## AIR HANDLING UNIT



TRUST AIR CONDITIONING EQUIPMENT CO. Prepared By: Engineering & R & D Department.

#### Content

- 1.	Trouble Shooting	 - 2
	After colos Carrios 9 Morrenty Densir	 _

توجه:

شرکت تراست حق تغییر مشخصات دستگاه ها را در جهت بهبود و ارتقای گیفیت برای خود محفوظ می دارد.



### 1. Trouble Shooting

Trouble	Cause	Solutions	
	Fan and fan bearing are loosen	1. Tighten	
	2. Foreign objects in screw or fan	2. Remove the objects	
	3. Air ducts and adjusting valves are loosen	3. Tighten	
	4. Two V-belt wheels are not on one line. The belts	4. Adjust	
	are too loose or too tight.	4. Aujust	
Abnormal	5. The soft connector of fan is too tight	5. Change the soft connector	
Noise	6. Fan speed is too high	6. Change the fan and belt	
	7. Dust in bearing caused by bad quality lubricating	7. Change the oil and clean the bearing	
	oil	7. Change the on and clean the bearing	
	8. Improper fan	8. Change the fan	
	Motor fan and motor foundation bolts and nuts	9. Fasten the bolts and nuts	
	are loose		
	The filter is too dirty	1. Wash the filter	
	Air duct is not well sealed	2. Check and	
Insufficient	3. Foreign object in the air duct; the damper is not	3. Check the pipes	
air volume	open	o. Official the pipes	
an volume	4. Fan Pulley	4. Change the motor phase	
	5. Improper selection of fan	5. Choose proper fan	
	6. Rotation speed is too low	6. Adjust the belt	
Air supply is	Improper selection of fan	Choose proper fan and air volume	
too large	2. Rotation speed is too high	2. Adjust the belt	
\\/oto#	1. Air speed is too high	1. Reduce the air volume	
Water	2. Condensing water cannot be discharged freely	2. Clear the dust inside the pipes	
Leakage	3. Air leakage	3. Seal the leakage	
	Water entering temperature is too high	1. Adjust the water temperature	
Low Cooling	2. Heat exchanger is too dirty	2, Clean the heat exchanger	
Capacity	3. Insufficient air volume	3. Increase the air volume	
	4. Improper unit selection	4. Select again	
Airflow	1. Air speed is too high	Increase the air supply area	
speed is too high.	2. Improper airflow design	2. Check the air duct design	
		1. Open the damper	
Air is fresh.	Insufficient fresh air volume	2. Wash the filter	
		3. Increase the air duct section	



#### 2. After-sales Service & Warranty Repair

- 1. Contact your dealer for service and maintenance. Improper repair and maintenance may cause water leakage, electric shock and fire.
- 2. If the unit is required to be moved or reinstalled, please contact your dealer. Improper installation may cause water leakage, electric shock and fire.
- 3. The product has a warranty period. After installation, the dealer will fill out the warranty application form and give to you. Please check all the listed items and keep it carefully.
- 4. The warranty period for a complete unit is 14 months starting from the purchase date. Please find details from the warranty application form.
- 5. During the warranty period, repair and changing components are free if it is caused by the quality of the unit. If you request for free repair, please inform your dealer and provide the warranty application form. Otherwise you may be charged even it is during the warranty period.
- 6. If request for repair, please provide the following information: Unit Model, Factory Code, Installation Date, Trouble Description, Your Name, Address and Telephone Number.
- 7. Provide whole life after-sales service. The cost of repair and maintenance may be charged after the warranty period.
- 8. Besides the daily maintenance, we suggest you to sign the maintenance contract with our professional service company. For details, please contact your dealer.



# Air Conditioning Systems Cooling & Heating

TRUST AIR-CONDITIONING EQUIPMENT CO. Shiraz office: 8 th floor, Alvand Blog., Dostan St.,

Moaliabad Ave., SHIRAZ, IRAN., Post code: 71877-14446

Tel.: +98-71-36341070 Fax.: +98-71-36341094

Tehran office: No. 19- koohe nour St.- Motahhari St.-

**TEHRAN, IRAN., Post code: 15876-73111** 

Tel.: +98-21-89389 Fax.: +98-21-88541903

Ahwaz office: No. 309- Kaveh St.- AHWAZ, IRAN., Post code: 61939-

47911

Tel.: +98-61-32230647-8 E-mail: info@trustacs.com

برترین نام و نشان های تجاری ایران Web site: http://www.trustacs.com برترین نام و نشان های تجاری ایران

برند برتر در اولین جشنواره بینالمللی در در نام و نشان های تجاری اسان

